

MusicMedic.com

Questions@MusicMedic.com

(910) 667-0270

Vortex Air Torch™ Instructions

Cautions:

The Vortex Air Torch™ is a tool and is intended to be used by professionals in a professional environment. Our customers have successfully used this tool for installing and removing pads, soldering, heating shrink tubing, re-hairing bows, and other miscellaneous heating projects. Once you get used to using your Air Torch™, you will find it to be an indispensable tool in your shop. .

1. The tip of the Air Torch™ gets very hot. Do not touch it or use it in a manner that will start a fire you are not intending to start.
2. Notice that the Air Torch™ turns ON when the handle is lifted, OR FALLS FROM, the holder. When you are not sitting at your bench and using this tool, make sure that the Air Torch™ is turned off.
3. When the Manual/Auto switch is engaged, the Air Torch™ will continue to run at your selected temperature. Do not leave the Air Torch™ running unattended. Be sure to return the Air Torch™ to Automatic mode and allow the unit to cool itself BEFORE turning off the power switch.



Controls:

- The black up and down buttons adjust Temperature in Celsius.
- The dial adjusts the speed of the air flow.
- The black switch on the Air Torch™ powers the machine on or off.
- The red square button changes between Manual and Automatic modes. In Manual mode, the Air Torch™ will continue to run even with the handset in the cradle.
- The three preset buttons (DO, RE, ME) allow you to save presets for both heat level and air flow speed.

Using the Air Torch:

1. Place the Air Torch™ gun in its holster with the desired tip on the gun.
2. Check that the power is turned off.
3. Plug in the unit.
4. Using the black buttons, adjust the temperature as desired.
5. Turn the air flow knob all the way clockwise to maximum air flow.
6. Remove the Air Torch™ gun from its cradle and the fan should start.
7. Aim the hot air where needed.
8. Adjust the temperature and air flow as needed.
To save a desired temperature/airflow preset, press and hold one of the three preset buttons until the machine beeps

When you are done using the gun:

1. Place the handle back on the cradle.
2. Make sure the Air Torch™ is in Automatic mode and is cooling.
3. Always allow the unit to cool itself.
4. When the fan stops, turn the power switch off.

30 Day Guarantee

With Free Shipping in U.S. and Canada and a 30 day guarantee you can order the tools you need, knowing that if it is not what you intended to purchase you can return it. After 30 days from purchase date products cannot be accepted for return or exchange.